

Slettnes fyr og Slettnes naturreservat

The map shows a coastal area with a red boundary enclosing a study area. Key features include:


- Water Bodies:** Sandfjorden, Sandvikvannet, Veslevikvannet, Gamvikvannet, Langdalsvatna, Lille Holmevatnet, Kovvatnet, Romelvatnet, and several smaller lakes and ponds.
- Landmarks and Place Names:** Vardnesodden, Slettnes, Korskmerket, Sandvikodden, Kjeholmen, Elvevågen, Flintodden, Gamvik, Koven, Kvalvika, Tverrvika, Tverrvikraet, Danielsneset, Holmevasshøgda, Grytvasshøgda, Langdalsvatna, Kråketua, Vardnessletta, Sandvikneset, Molvik, Steinvågen, Veslevikhaugen, Sandvikryggen, Sandfordryggen, Olagrunnen, Sandgrunnen, Sandbakkvika, and Vardnesodden.
- Infrastructure:** A road network is visible, including a yellow line representing a main road and several smaller roads.
- Topography:** Contour lines indicate elevation, with labels such as 33, 35, 42, 45, 41, 17, 27, 54, 81, 108, and 118.
- Study Area:** A red boundary outlines the study area, which includes the Slettnes area and surrounding water bodies and land.

Fredete bygninger på Slettnes fyr




Figur 2 På slettens fyr står det til sammen 8 bygninger som er fredet etter kulturminneloven (her merket som røde trekanter).

Område fredet etter kulturminneloven



Figur 3 Området fredet som kulturminne er markert med lilla farge. Blå dråpe med firkant inni viser at det er bygninger og infrastruktur. Rød dråpe med R viser at det er arkeologiske kulturminner. Rød stiplet strek viser sikringssonen rundt de arkeologiske kulturminnene. Her er det et dobbeltvern, dvs. at området er fredet etter både kulturminneloven og naturvernloven (naturreservat).

Bygninger på Slettnes fyr



Figur 4 Bygninger på Slettnes fyrstasjon.

Bygninger og anlegg er unntatt fra verneforskriften



Figur 5 Bygninger og anlegg omfattes ikke av verneforskriften for Slettnes naturreservat. Innenfor gul stiptet linje er det på bakkeplan anlagt gangveger i betong og plener/gressletter. Det finnes også noen mindre områder med grus/stein.



Figur 6 Omtrentlig plassering av dagens gjerde/port rundt Slettnes fyr er markert med orange prikket linje.



Figur 7 Foto av dagens gjerde rundt Slettnes fyr. Som en ser av fotoet, er gjerdet i svært dårlig forfatning.